Wheel Horse Service Bulletins 1961 - 1990: #200 Issued: March 1977

Model A-90 and Model A-100 Belt Life

Previous Table of Contents Next

VIN #62-08BP01, 72-08BP01 and VIN #62-10BP01, 72-10BP01

To All Dealers:

- 1. To insure long mower belt life on the above Model A Series lawn tractors, the following check list is of most importance and should be made <u>prior to delivery</u>.
- 2. Be sure <u>engine</u> is <u>not</u> running when making the following checks.
- 2.1 Check tire pressure by placing unit on a flat surface. Front tires 12 lbs., rear tires 9 lbs.
- 2.2 Place mower in center cut position.
- 2.3 Rotate center mower blade so that it is parallel to the side of the tractor (pointing forward). Measure distance between the blade tip at the front and the floor. Measure distance at the other end of the same blade and the floor. The blade should be 1/8" lower at the front. If adjustment is needed, adjust the rear lift rod, part #105536, to obtain correct front to rear attitude of the mower.
- 2.4 Check mower level (side to side) by adjusting right hand lift studs, part #105928. Right and left mower blades should be equal distance from the floor.
- 2.5 Lower pulley, part #105465, on integral shaft, part #103711, should be checked to be sure pulley hub extends 1/4" lower than the end of the shaft. Upper pulley, part #105465, should be even with the top of integral shaft, part #103711.
- 2.6 Engage mower and check mower drive belt tension, part #105477. There should be 1/8" clearance between flat washer and welded bracket on mower deck. If correction is required, adjust rod, part #103477.
- 2.7 All belt guides should clear the belt by 1/16" to 1/8" when mower is engaged.
- 3. Reference
- 3.1 Part manuals.
- 3.2 Microfiche
- 3.2.1 VIN #62-08BP01, VIN #62-10BP01 Card #26 (Red) Grid C-7-8, D-5-6-7-8
- 3.2.2 VIN #72-08BP01, VIN #72-10BP01 Card #32 (Red) Grid A-9-10
- 3.2.3 VIN #72-08BP01, VIN #72-10BP01 Card #11 (Pink) Grid A-5-6-7-8

Wheel Horse Service Bulletins 1961 - 1990: **#206** Issued: August 1977

Model A-90, A-100 Lawn Tractors - Mower Drive Belt Jumping

Previous Table of Contents Next

ROTARY MOWER VIN #65-36XS02-03

ROTARY MOWER VIN #65-36MR02-03

ROTARY MOWER VIN #75-36XS01

ROTARY MOWER VIN #75-36MR01


To All Dealers

1. Problem

1.1 Rotary Mower Drive Belt Part #105477, has been known to jump off Mower Drive Pulley, Part #105465 upon engagement. This problem has occured even after proper setup and adjustments have been made according to Service Bulletin 200.

2. Solution

2.1 Replace Mower Drive Pulley, Part #105465, with new deep groove pulley, Part # 106524 as shown in sketch #2.



- 2.2 Order new Pulley, Part #106524, from your Distribution Center.
- 2.3 Installation of new Pulley, Part #106524, requires modification of Support and Brake Lining Assembly, Part #105469. Cut off as shown in sketch #1. This insures proper brake

contact with pulley.

2.4 If a new Drive Belt is installed, Part #105477, it is suggested the Belt Tension be readjusted after 10-15 minutes running.

3. References

Parts list form 803673R, Page 4 & 6.

Parts list form 803466, Page 19,21,23 & 25.

Microfiche Card Pink Grid A-5, A-6, A-7 & A-8.

Microfiche Card Red 26, Grid D-5, D-6, D-7, D-8, D-9, D-10, D-11 & D-12

Service Bulletin 200

- 4. Reimbursement
- 4.1 File A Standard Warranty Claim.
- 4.2 Operation Number 21201-.3 Hour.

Operation Number 21230-.3 Hour.

105132-37 ASSEMBLY INSTRUCTIONS

THESE SERVICE ASSEMBLIES ARE USED TO REPLACE THE 104891 SPINDLE (DOUBLE "D" SHAFT), USED ON ALL 1976 AND PRIOR, AS WELL AS 1977 75-42MR01, 75-42MS01, 75-48MS01, AND 75-48XS01 42" AND 48" MOWERS.

SERVICE ASSEMBLY IDENTIFICATION:

```
105134 42" SIDE DISCHARGE RIGHT OR LEFT SPINDLE
```

105135 42" SIDE DISCHARGE CENTER SPINDLE


105137 42" REAR DISCHARGE RIGHT OR LEFT SPINDLE

105136 42" REAR DISCHARGE CENTER SPINDLE

105133 48" SIDE DISCHARGE RIGHT OR LEFT SPINDLE

105132 48" SIDE DISCHARGE CENTER SPINDLE

PARTS IDENTIFICATION AND ASSEMBLY ARE SHOWN ON REVERSE SIDE. INSTRUCTIONS FOR INSTALLING NEW SPINDLE ASSEMBLIES ARE DESCRIBED IN SERVICE BULLETIN 207.



| ITEM NO. | PART NO. | DESCRIPTION | | | | | | |
|----------|----------|-------------------------------|--|--|--|--|--|--|
| 1 | 915640 | E.S. Nut 3/4-16 | | | | | | |
| 2 | 106075 | Seal-Double Lip | | | | | | |
| 3 | 106070 | Spacer/Seal | | | | | | |
| 4 | 106085 | Ball Bearing (Non-Sealed) | | | | | | |
| 5 | 106063 | Spindle Housing | | | | | | |
| 6 | 106069 | Spacer | | | | | | |
| 7 | 106084 | Ball Bearing (Sealed) | | | | | | |
| 8 | 936028 | Internal Snap Ring | | | | | | |
| 9 | 106068 | Blade Spacer | | | | | | |
| 10 | 106067 | Spindle Cup | | | | | | |
| 11 | 4459 | Grease Fitting | | | | | | |
| 12 | 937156 | Hi-Pro Key 3/16 x 5/8 | | | | | | |
| 13 | 108849 | Spindle Shaft | | | | | | |
| 14 | 915090 | Jam Nut 3/4-16 | | | | | | |
| 15 | 920257 | Special Washer 1 1/4 in. O.D. | | | | | | |
| 16 | 920258 | Special Washer 1 1/2 in. O.D. | | | | | | |
| | | | | | | | | |

Wheel Horse Service Bulletins 1961 - 1990: #207b Issued: April 1986

42" and 48" Rotary Mowers Greaseable Spindles for Replacement of 100710, 102776, 104891, 106062 & 108848 Spindle Assemblies

Previous Table of Contents Next

THIS BULLETIN SUPERSEDES BULLETIN 207A, ISSUED MARCH, 1984

1. Subject

1.1 Service Assemblies to convert 42" and 48" mowers from non-greaseable spindles to greaseable construction are available (see paragraph 2.3). Mowers effected are:

All 1976 and prior 42" and 48" rotary mowers. 1977 Mower VIN's 75-42MS01, 75-42 MR01, 75-48MS01, 75-48XS01. (Double "D" Spindle Shaft denotes non-greaseable construction except on 1963-72 mowers with 4299/8139 cast iron spindle housing.)

1.2 Service Assemblies to convert 42" and 48" mowers to the current production spindle (metric bearing construction) replace the assemblies in paragraph 2.3 (see paragraph 2.4). These Service Assemblies can be used on all 1984 and prior 42" and 48" rotary mowers.

2. Service Action

- 2.1 The spindle service assemblies consist of a mower blade, pulley, spindle and necessary hardware. Installation instructions/replacement parts list is furnished with each assembly.
- 2.2 It is recommended all three (3) spindles be changed at the same time because of the difference in spindle shafts. This will avoid the need to order two (2) different blade kits to service a mower with mixed spindles.
- 2.3 Spindle Service Assemblies-Standard Bearing Construction

42" Rear Discharge Mower S/A 105136 Center Spindle (Order one) S/A 105137 RH/LH Spindle (Order two) Replacement Blade Kit #106635 42" Side Discharge Mower S/A 105135 Center Spindle (Order one) S/A 105134 RH/LH Spindle (Order two) Replacement Blade Kit #106636 48" Side Discharge Mower S/A 105132 Center Spindle (Order one) S/A 105133 RH/LH Spindle (Order two)

Replacement Blade Kit #106637

2.4 Spindle Service Assemblies-Metric Bearing Construction

42" Rear Discharge Mower

S/A 110984 Center Spindle (Order one) S/A 110985 RH/LH Spindle (Order two) Replacement Blade Kit #106635

42" Side Discharge Mower

S/A 110982 Center Spindle (Order one) S/A 110983 RH/LH Spindle (Order two) Replacement Blade Kit #106636

48" Side Discharge Mower

S/A 110980 Center Spindle (Order one) S/A 110981 RH/LH Spindle (Order two) Replacement Blade Kit #106637

2.5 Reference Information

- 2.4.1 Greaseable Spindle installation information, replacement parts list-see S/A 105132-105137 instruction sheet, Fiche Card 5 Orange.
- 2.4.2 1973-1977 original equipment spindle information, #100710, 102776, 104891 spindles-See Service Bulletin 211C.
- 2.4.3 1963-1972 original equipment spindle information, 34299/8139 housing, 4393/5875 spindle shaft, S/A 101550, 101685, 101686, 109094 spindle/spindle assemblies See Service Bulletin 221B.
- 2.4.4 Refer to Spindle Identification Chart, literature partnumber 810415R1, for further spindle information.

Wheel Horse Service Bulletins 1961 - 1990: #400 Issued: October 1986

Muffler - Wheel Horse Part Number 105500 Used on Model A-100 VIN
62-10BP01 & 72-10RP01

<u>Previous</u> <u>Table of Contents</u> <u>Next</u>

- 1. Subject
- 1.1 Muffler 105500 is no longer available.
- 1.2 A Briggs & Stratton muffler is an acceptable substitute.
- 2. Service Action
- 2.1 Order Briggs & Stratton muffler 391569 from your supplier of Briggs & Stratton parts.

| POLITICAL | MERVICE MARACHA | SALES MANAGER | PARTS MANAGER | CHAEF MECHANIC | MC-MIE NO 1 | MEDIANIC NO 2 | MECHANIC | MECHANIC NO 4 | RETURN THE TO |
|-----------------|--------------------|------------------|------------------|-------------------|----------------|------------------|----------|------------------|------------------|
| IMITIAL HERE | | | | | | | | | |