

---

Wheel Horse Service Bulletins 1961 - 1990: **#195** Issued: December 1976  
**Sundstrand Transmission - Sudden Loss of Power - B, C & D Series Models**

[Previous](#)   [Table of Contents](#)   [Next](#)

---

To All Dealers:

1. Problem

1.1 Sudden loss of power associated with loss of charge and/or lift pressure due to failure of motor shaft snap ring, part #200206.

2. Solution

2.1 Replace original snap ring #200206 with Service Assembly #105124.

2.2 Service Assembly #105124 consists of part #200247 shaft and part #200246 snap ring. Both the shaft and snap ring are new parts.

2.3. Inspect for other possible damage and repair as required.