
Wheel Horse Service Bulletins 1961 - 1990: **#402** Issued: March 1987

Mower Belt Installation - 37" Side Discharge Mower

[Previous](#) [Table of Contents](#) [Next](#)

05-07SC01

Subject


1.1 The 05-57SC01, 37" side discharge mower is driven by one (1) HAA double V-belt, Wheel Horse part #111178.

1.2 The above #111178 belt will fail prematurely if improperly installed.

Service Action

2.1 Refer to the belt routing illustration below for the correct belt routing. NOTE: For reference, one side of the belt has been shaded.

2.2 The Wheel Horse belt part #111178 appears on the shaded side of the belt.



ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	CHIEF MECHANIC	MECHANIC NO 1	MECHANIC NO 2	MECHANIC NO 3	MECHANIC NO 4	RETURN THIS TO
INITIAL HERE →									