


WIRING DIAGRAM - D-160



SWITCH POSITION	ELECTRICAL CONN BETWEEN TERMINALS
OFF	NONE
RUN	B+R+I+A
START	B+R+I+S

