

## **Transmission oil filter**

The first WH filter was #5990 from 1965-72.  
This was replaced by WH #102819 1973-80.  
This was replaced by WH #108335 1980-92.  
This was replaced by Toro #79-5270 1992-on.

If you go to Wix the only filter that is a direct replacement without a bypass valve is 108335 = Wix 51410 = Napa 1410.

If you have a filter without an internal bypass on the transmission and it plugs up or becomes restricted the operator will notice the reduced performance. Change filter and away you go again.

If you have a filter with an internal bypass on the transmission and it plugs up, the bypass opens and allows the dirt and oil to continue on into the pump potentially damaging it. The operator will notice the reduced performance and repair or replace transmission and go again.

WH 5990 = Wix 51307 for direct replacement with bypass  
WH 102819 = Wix 51521 for direct replacement with bypass  
WH 108335 = Wix 51410 for direct replacement without bypass  
Toro 79-5270 = Wix 51521 for direct replacement with bypass

I would definitely use the Wix 51410 or Napa 1410 for all the hydro transmissions.

Garry