


## January 27, 1961

## TO ALL DEALERS & DISTRIBUTORS

## SUBJECT: 5007 TRANSMISSIONS & REPLACEMENTS

ALL #5007 Transmissions assembled on the 1961 tractors, Models 551 & 701, are being shipped from the factory WITHOUT gear lubricant. These tractors are tagged with a caution tag on the gear shift lever.



ALL replacement transmissions are also shipped WITHOUT lubricant, IN CARTONS with the shift lever removed for easier packaging. It is suggested that you drain lubricant, remove shift and repack defective unit together with the shift stick in the shipping carton, tagged with a green return tag (furnished by your distributor) and return to your distributor for proper credit.

## NOTE TO DEALER:

You should now have in your possession Service Bulletins #11, #12, #13 and #19. In the future, as in the past, your bulletins will not necessarily be in numerical sequence as some bulletins pertain to the distributor only.

PARTS & SERVICE DEPARTMENT

WHEEL HORSE PRODUCTS, INC.